



VEHICLE INSPECTION REPORT

KF18JXJ

Vauxhall Grandland X 1.2 Turbo SE 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/06/2018	Body Style	Hatchback	Last service miles	52,016
Year	2018	Keys	2	MOT Due	Expired
Mileage	56,050 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	7	Doors	5
VIN	W0VZRHNY0JS101609	Last service date	30/10/2024		

£65 ADDITIONAL FEE. Last service 30/10/2024 at 52016 miles (7 services (6 main dealer)).

Tyres

NSF	GOODYEAR	4.0mm
NSR	BUDGET	3.0mm
OSF	GOODYEAR	4.0mm
OSR	HIFLY	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Dented
With Paint Damage



2: Bumper Front
Dented
With Paint Damage



3: Bumper Front Grill
Broken
Replace



4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Chipped
1 To 5



6: Door nsf
Poor Previous Repair
Poor Paint



7: Door nsr
Dented
2 Or Less UpTo 10mm




8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint



14: Boot Lid
Chipped
1 To 5

No Image



15: Boot Lid
Scratched
Over 25mm Not Thru Paint

16: Qtr Panel osr
Dented
Between 10mm + 30mm



17: Wheel osr
Scratched
Up To 50mm



18: Qtr Panel osr
Dented
2 Or Less UpTo 10mm

No Image



19: Door osr
Scratched
Over 25mm Not Thru Paint

20: Door osf
Dented
Over 2 UpTo 10mm

No Image

21: Door osf
Scratched
Over 25mm Not Thru Paint




22: Roof
Scratched
Over 25mm Thru Paint



23: Wheel osf
Scratched
Over 50mm

No Image

24: Wing osf
Scratched
Over 25mm Not Thru Paint



25: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK