



VEHICLE INSPECTION REPORT

GP19DNY

Suzuki Vitara 1.0 Boosterjet SZ-T 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	29/05/2019	Body Style	Hatchback	Last service miles	42,068
Year	2019	Keys	2	MOT Due	05/06/2026
Mileage	52,408 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	2	Doors	5
VIN	TSMLYD01S00653562	Last service date	20/05/2024		

£65 ADDITIONAL FEE. Last service 20/05/2024 at 42068 miles (2 services (1 main dealer). Brakes noisy while reversing

Tyres


NSF	BUDGET	2.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips




2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Scratched
Over 25mm Thru Paint



4: Qtr Panel osr
Chipped
1 To 5




5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Wheel osr
Scratched
Up To 50mm



7: Door osr
Chipped
1 To 5



8: Door osr
Scratched
Over 25mm Not Thru Paint



9: Door osf
Dented
With Paint Damage



10: Wing osf
Chipped
1 To 5




11: Wheel osf
Scratched
Over 50mm



12: Bonnet
Chipped
1 To 5




13: Bumper Front
Chipped
Multiple Chips



14: Bumper Front
Scratched
Over 25mm Not Thru Paint



15: Wing nsf
Chipped
1 To 5




16: Wing nsf
Scratched
Over 25mm Not Thru Paint



17: Wheel nsf
Scratched
Over 50mm



18: Door nsf
Chipped
1 To 5



19: Door nsf
Scratched
Over 25mm Not Thru Paint



20: Door nsr
Chipped
1 To 5

No Image



21: Door nsr
Scratched
Over 25mm Not Thru Paint

22: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image



23: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint

24: Wheel nsr
Scratched
Up To 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK