

VEHICLE INSPECTION REPORT

LS66KWD

Peugeot 2008 1.6 BlueHDi 100 Allure 5dr

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE
		V5	Present	_	
Details					
Reg. date	30/09/2016	Body Style	Hatchback	Last service miles	54,499
Year	2016	Keys	2	MOT Due	29/09/2026
Mileage	77,362 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Electronic / Online	Gears	5
Colour	BLACK	Number of stamps	1	Doors	5
VIN	VF3CUBHY6GY146169	Last service date	27/07/2023		

£100 ADDITIONAL FEE

Last service 27/07/2023 at 54,499 miles- 1 service confirmed by Saabtech, St Leonards on Sea Air bag tensioner fault on dash

Service on dash

_		
	Vrac	
	yı cə	

NSF	BUDGET	5.0mm	
NSR	BUDGET	4.0mm	
OSF	BUDGET	5.0mm	
OSR	BUDGET	4.0mm	
Spare			

Features

- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Cruise control
- Steering wheel mounted controls

 Audio remote control
 Electric door mirrors

 Air conditioning
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS


- Air conditioning
 Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbagRemote central locking
- Rear parking sensor
 Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags Partial leather seat trim

Photos












Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front Scratched Over 100mm Thru Paint

3: Wing nsf Chipped 1 To 5

4: Wing nsf Scratched Over 25mm Not Thru Paint



5: Wheel nsf Scratched Over 50mm



6: Door Mirror Assy nsf Scratched (Painted) Over 25mm Thru Paint



7: Door nsf Chipped Multiple Chips



8: Door nsr Chipped Multiple Chips



9: Wheel nsr Scratched Over 50mm




10: Qtr Panel nsr Chipped 1 To 5

11: Qtr Panel nsrScratchedOver 25mm Not Thru Paint



12: Bumper Rear Scratched 25 to 100mm Thru Paint

No Image





14: Boot Lid Chipped Multiple Chips

15: Qtr Panel osr Chipped 1 To 5

16: Qtr Panel osrScratchedOver 25mm Not Thru Paint



17: Wheel osr Scratched Over 50mm



18: Door osr Chipped Multiple Chips



19: Door osf Chipped Multiple Chips



20: Wing osf Chipped 1 To 5

21: Wing osf Scratched Over 25mm Not Thru Paint



22: Wheel osf Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs OK		Gearbox 1st and Reverse Test	
Brakes OK		Clutch Slip Test from Static	
Turbo Boosting		Gearbox Static Gear Selection (engine running)	
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK