

#### 19c Commercial Road Eastbourne BN21 3XE 01323 520295 | no-reply@ebca.co.uk

# **VEHICLE INSPECTION REPORT**



## **Mercedes-Benz M-Class ML 350 INSPIRATION**

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		<b>3</b>
		V5	TBC		
Details					
Reg. date	24/09/2004	Colour	SILVER	MOT Due	28/04/2026
Year	2004	VIN	WDC1631572A488004	Gearbox	AUTOMATIC
Mileage	99,291 Miles Warranted	Body Style	Estate	Gears	5
		Keys	3		
Fuel Type	Petrol	-			

Possible exhaust leak

Tyres			
NSF	CONTINENTAL	3.0mm	
NSR	GENERAL TIRE	4.0mm	
OSF	CONTINENTAL	2.0mm	
OSR	GENERAL TIRE	4.0mm	
Spare			

## Features

<ul> <li>Heated front seat</li> </ul>	• PAS	<ul> <li>Radio/Cassette</li> </ul>	<ul> <li>Body coloured bumpers</li> </ul>
<ul> <li>Electric door mirrors</li> </ul>	<ul> <li>Full size spare wheel</li> </ul>	<ul> <li>Air conditioning</li> </ul>	<ul> <li>Climate control</li> </ul>
<ul> <li>Electrically adjustable drivers se</li> </ul>	at <ul> <li>Electrically adjustable passenge</li> </ul>	er • Front electric windows	<ul> <li>Front head restraints</li> </ul>
	seat		
<ul> <li>Rear electric windows</li> </ul>	<ul> <li>Rear headrests</li> </ul>	<ul> <li>Metallic Paint</li> </ul>	<ul> <li>3x3 point rear seat belts</li> </ul>
<ul> <li>Drivers airbag</li> </ul>	<ul> <li>Isofix child seat anchor points</li> </ul>	<ul> <li>Passenger airbag</li> </ul>	<ul> <li>Side airbags</li> </ul>
Central locking	Remote central locking	Leather seat trim	Alloy wheels
e e i la le e i la g	i toinioto ooninai iooning		

#### **Photos**












## **Condition Check**



### **Damage Photos**





1: Bonnet Chipped Multiple Chips

2: Bumper Front Poor Previous Repair Paint Flake





3: Wheel osf Scratched Over 50mm





5: Door osr Chipped 1 To 5



6: Qtr Panel osr Scratched UpTo 25mm Thru Paint



7: Wheel osr Scratched Over 50mm



8: Bumper Rear Poor Previous Repair Poor Paint





9: Qtr Panel nsr Chipped 1 To 5

10: Wheel nsf Scratched Over 50mm






11: Door nsr Chipped 1 To 5



13: Screen Front Chipped UpTo 10mm



14: Wheel nsf Scratched Over 50mm

# No Image

15: Wing nsf Chipped 1 To 5

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition Odour Average No

#### **Vehicle Inspection Report**

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK