



VEHICLE INSPECTION REPORT

GU15VWK

Mazda 3 2.0 Sport Nav 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/03/2015	Body Style	Hatchback	Last service miles	68,170
Year	2015	Keys	2	MOT Due	30/03/2026
Mileage	115,072 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	2	Doors	5
VIN	JMZBM546611201833	Last service date	25/04/2023		

Last service 25/04/2023 at 68,170 miles- 2 services

Tyres

NSF	BUDGET	2.0mm
NSR	HANKOOK	3.0mm
OSF	BUDGET	3.0mm
OSR	HANKOOK	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos




1: Bonnet
Chipped
1 To 5



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wing nsf
Chipped
1 To 5




4: Wing nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Dented
2 Or Less UpTo 10mm

No Image



9: Door nsr
Scratched
Over 25mm Not Thru Paint

10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Dented
Over 30mm



12: Bumper Rear
Chipped
Multiple Chips

No Image


No Image

13: Bumper Rear
Scratched
Over 25mm Not Thru Paint

14: Boot Lid
Scratched
Over 25mm Not Thru Paint




15: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Scratched
Up To 50mm



18: Door osr
Dented
With Paint Damage



19: Door osr
Poor Previous Repair
Poor Paint



20: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



21: Wing osf
Poor Previous Repair
Poor Paint



22: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK