



VEHICLE INSPECTION REPORT

RE14TBU

Porsche Cayenne Platinum Edition Diesel 5dr Tiptronic S

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	13/06/2014	Body Style	Estate	Last service miles	73,317
Year	2014	Keys	2	MOT Due	19/02/2026
Mileage	89,941 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	8
Colour	BLACK	Number of stamps	6		
VIN	WP1ZZZ92ZELA49411	Last service date	20/03/2024		

£65 ADDITIONAL FEE. Last service 20/02/2024 at 73317 miles (6 services (1 main dealer). Dashboard damaged

Tyres

NSF	YOKOHAMA	2.0mm
NSR	YOKOHAMA	3.0mm
OSF	PIRELLI	2.0mm
OSR	YOKOHAMA	2.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Electric sunroof
- Electrically adjustable drivers seat
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Heated front seat
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Door Pad nsf
Torn
Over 10mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wheel nsf
Scratched
Up To 50mm




5: Wing nsf
Chipped
1 To 5



6: Wing nsf
Scratched
Over 25mm Not Thru Paint




7: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



8: Door nsf
Dented
Over 30mm



9: Door nsr
Chipped
1 To 5




10: Door nsr
Scratched
Over 25mm Not Thru Paint



11: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



12: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



13: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint




14: Wheel nsr
Scratched
Over 50mm



15: Bumper Rear
Scratched
Over 100mm Thru Paint




16: Boot Lid
Scratched
UpTo 25mm Thru Paint



17: Boot Lid
Scratched
Over 25mm Not Thru Paint



18: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



19: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



20: Wheel osr
Scratched
Up To 50mm



21: Door osr
Dented
Over 2 UpTo 10mm

No Image

22: Door osr
Scratched
Over 25mm Not Thru Paint



23: Door osf
Chipped
1 To 5

No Image

24: Door osf
Scratched
Over 25mm Not Thru Paint



25: Wing osf
Chipped
1 To 5

No Image

26: Wing osf
Scratched
Over 25mm Not Thru Paint



27: Wheel of
Scratched
Over 50mm



28: Other
N/A
N/A

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		