

VEHICLE INSPECTION REPORT

WR22CFX

Toyota RAV4 2.5 VVT-i Hybrid Design 5dr CVT

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		GRADE GRADE
		V5	Present		
Details					
Reg. date	27/05/2022	Body Style	Estate	Last service miles	79,818
Year	2022	Keys	2	MOT Due	26/05/2026
Mileage	86,327 Miles Warranted	Service history	Yes	Gearbox	CVT
		Service documents	Service Book	Gears	1
Fuel Type	Hybrid Electric	Number of stamps	4		
Colour	BLUE	Last service date	27/05/2025		
VIN	JTMR63FV40D524447		· · · · · · · · ·		

Last Service - 27.05.2025 at 79818 miles (4 main dealer services)

Tyres

NSF	JOYROAD	4.0mm	
NSR	FARROAD	4.0mm	
OSF	JOYROAD	2.0mm	
OSR	BUDGET	4.0mm	
Spare			

Features

- Bluetooth connection
- PAS
- Digital radioClimate control
- Height adjustable drivers seat
 3x3 point rear seat belts
 Isofix child seat anchor points

- Remote central locking
- Cruise control
- Rear wiper Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
 Steering wheel mounted controls
 Electric door mirrors
 Park assist camera
 Audio remote control
 Air conditioning
- · Front electric windows
- Rear headrestsCurtain airbags
- Traction control
- Alloy wheels

- Air conditioningFront head restraints
- Metallic PaintDrivers airbag
- Central locking

Photos






















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf Scratched Over 50mm



4: Wing nsf Chipped 1 To 5



5: Door nsf Chipped 1 To 5

No Image

6: Door nsf Scratched Over 25mm Not Thru Paint




7: Door nsr Chipped 1 To 5

No Image

8: Door nsr Scratched Over 25mm Not Thru Paint



9: Wheel nsr Scratched Up To 50mm



10: Qtr Panel nsr Poor Previous Repair Poor Paint



11: Bumper Rear Chipped Multiple Chips

No Image

12: Bumper Rear Scratched Over 25mm Not Thru Paint




13: Boot Lid Dented Over 30mm

No Image

14: Qtr Panel osr Scratched Over 25mm Not Thru Paint



15: Wheel osr Scratched Up To 50mm



16: Door osr Poor Previous Repair Poor Paint



17: Door osf Dented Over 30mm



18: Wing osf Chipped 1 To 5



19: Screen Front Chipped UpTo 10mm



20: Wheel osf Scratched Over 50mm

Interior

Carpet Condition Upholstery Condition Average **Seat Condition** Odour Average

Average No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK