



VEHICLE INSPECTION REPORT

GX64FCG

Toyota Auris 1.8 VVTi Hybrid Excel 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/12/2014	Body Style	Hatchback	Last service miles	43,371
Year	2014	Keys	2	MOT Due	04/11/2025
Mileage	46,821 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	BLUE	Number of stamps	10	Doors	5
VIN	SB1MS3JE00E122372	Last service date	30/10/2024		

Last Service - 30.10.2024 at 43371 miles (10 main dealer services)

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Leather seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking

Photos






Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Poor Paint




3: Wing nsf
Poor Previous Repair
Poor Paint



4: Wheel nsf
Scratched
Over 50mm




5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint




7: Door nsr
Chipped
1 To 5



8: Door nsr
Scratched
Over 25mm Not Thru Paint



9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



10: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Scratched
Over 100mm Thru Paint



13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint

No Image



15: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Between 10mm + 30mm

No Image

18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Door osf
Poor Previous Repair
Poor Paint



20: Wing osf
Chipped
1 To 5



21: Screen Front
Chipped
UpTo 10mm



22: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		