



VEHICLE INSPECTION REPORT

YA63VCX

Nissan Juke 1.5 dCi N-Tec 5dr [Start Stop]

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	31/01/2014	Body Style	Hatchback	Last service miles	65,432
Year	2014	Keys	1	MOT Due	29/05/2026
Mileage	91,396 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	6	Doors	5
VIN	SJNFCAF15U6484193	Last service date	19/10/2022		

Last Service - 19.04.2022 at 65432 miles (6 services)
Squeaky noise and vibration at idle

Tyres



NSF	MICHELIN	3.0mm
NSR	BUDGET	4.0mm
OSF	MICHELIN	2.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Remote central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Other
N/A
N/A



4: Wing nsf
Chipped
1 To 5



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Door nsf
Dented
With Paint Damage



8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Bumper Rear
Poor Previous Repair
Paint Flake



13: Boot Lid
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Chipped
1 To 5

No Image



15: Qtr Panel osf
Scratched
Over 25mm Not Thru Paint

16: Wheel osf
Scratched
Over 50mm



17: Door osf
Chipped
Multiple Chips



18: Door osf
Chipped
Multiple Chips



19: Wing osf
Chipped
1 To 5

No Image

20: Wing osf
Scratched
Over 25mm Not Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Screen Front
Chipped
UpTo 10mm



23: Roof
Rusted
UpTo 5mm



24: Wing Front Arch Extension os
Broken
Replace

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK