



VEHICLE INSPECTION REPORT

GV14ACF

Toyota Auris 1.8 VVTi Hybrid Icon 5dr CVT Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	27/06/2014	Body Style	Hatchback	Last service miles	84,721
Year	2014	Keys	2	MOT Due	01/02/2026
Mileage	120,659 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Hybrid Electric	Service documents	Service Book	Gears	1
Colour	BRONZE	Number of stamps	4	Doors	5
VIN	SB1MS3JE00E104065	Last service date	26/03/2022		

Last Service - 26.03.2022 at 84721 miles (4 main dealer services)

Tyres

NSF	BUDGET	3.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Dented
Over 2 UpTo 10mm



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Poor Previous Repair
Poor Paint



11: Boot Lid
Dented
Over 2 UpTo 10mm



12: Roof
Dented
Between 10mm + 30mm




13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Up To 50mm




15: Door osr
Chipped
1 To 5




16: Door osr
Scratched
Over 25mm Not Thru Paint



17: Door osf
Chipped
1 To 5



18: Door osf
Scratched
Over 25mm Not Thru Paint



19: Wing osf
Scratched
Over 25mm Not Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK