



VEHICLE INSPECTION REPORT

LD57AEF

Toyota Auris 1.6 VVTi TR 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	20/09/2007	Body Style	Hatchback	Last service miles	68,899
Year	2007	Keys	2	MOT Due	20/09/2026
Mileage	70,653 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	GREY	Number of stamps	15	Doors	5
VIN	SB1KV56E80F029645	Last service date	19/09/2024		

Last Service - 19.09.2024 at 68899 miles (15 services)
Strong smell of cigarettes

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking

Photos





Condition Check



Damage Photos



1: Roof Lining
Burn
UpTo 3mm



2: Carpets Front
Scuffed
Over 25mm



3: Centre Console Front
Scuffed
Over 25mm



4: Bonnet
Scratched
UpTo 25mm Thru Paint



5: Bumper Front Moulding
Broken
Replace



6: Bumper Front
Scratched
Over 100mm Thru Paint



7: Wheel nsf
Scratched
Over 50mm



8: Wing nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsf
Chipped
Edge Chip



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
With Paint Damage



12: Bumper Rear
Dented
With Paint Damage



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Dented
Over 30mm



17: Sill os
Scratched
Rusted



18: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



19: Wing osf
Scratched
UpTo 25mm Thru Paint



20: Roof
Chipped
1 To 5



21: Screen Front
Chipped
UpTo 10mm

22: Door osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition Poor
Seat Condition Average

Upholstery Condition Average
Odour Yes

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK