



VEHICLE INSPECTION REPORT

CY65KPG

Volkswagen Golf 2.0 TDI 184 GTD 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present

nama
GRADE
3

Details

Reg. date	01/09/2015	Body Style	Estate	Last service miles	106,829
Year	2015	Keys	2	MOT Due	12/09/2026
Mileage	115,428 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	GREY	Number of stamps	10		
VIN	WVWZZZAUZGP500366	Last service date	18/02/2025		

£65 ADDITIONAL FEE

Last service 18/02/2025 at 106,829 miles- 10 services (6 main dealer)

Tyres


NSF	UNIROYAL	4.0mm
NSR	SAILUN	4.0mm
OSF	UNIROYAL	4.0mm
OSR	SAILUN	4.0mm
Spare		

Features


- Bluetooth connection
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Dented
Between 10mm + 30mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Chipped
1 To 5



7: Door nsr
Chipped
1 To 5



8: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Chipped
1 To 5



12: Qtr Panel osr
Chipped
1 To 5




13: Wheel osr
Scratched
Over 50mm



14: Door osr
Chipped
1 To 5



15: Door osf
Chipped
1 To 5



16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wing osf
Chipped
1 To 5



18: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK