

## VEHICLE INSPECTION REPORT

FL16WZS

## **Toyota Avensis 2.0D Business Edition Plus 4dr**

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present	<u> </u>	
Details					
Reg. date	21/03/2016	Body Style	Saloon	Last service miles	26,391
Year	2016	Keys	2	MOT Due	15/02/2026
Mileage	35,054 Miles Warranted	Service history	Yes	Gearbox	MANUAL
		Service documents	Service Book	Gears	6
Fuel Type	Diesel	Number of stamps	5	Doors	4
Colour	SILVER	Last service date	16/02/2022		
VIN	SB1BT76L80E009966				

Last Service - 16.02.2022 at 26391 miles (5 services)

_	-			
	W	r	0	c
	y		·	J

NSF	LAUFENN	5.0mm
NSR	BUDGET	5.0mm
OSF	LAUFENN	6.0mm
OSR	BUDGET	5.0mm
Spare		

## **Features**

- Bluetooth connection
- PAS
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat beltsESP
- Side airbags
- · Alloy wheels

- Steering wheel mounted controls
   Front fog lights

  Front head restarting to the second secon
- Front head restraints
- Steering wheel rake adjustment
- Isofix child seat anchor points
- Central locking

- Digital radio
  Air conditioning
  Height adjustable drivers seat
  Steering wheel reach adjustment
  Curtain airbags
  Passenger airbag
  Pemote central locking


- Remote central locking
- Park assist camera
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint Drivers airbag
- Rear airbags
- Leather seat trim

#### **Photos**










## **Condition Check**



## **Damage Photos**



1: Bumper Front Scratched Over 100mm Thru Paint



2: Wheel nsf Scratched Over 50mm

# No Image

3: Wing nsf Scratched Over 25mm Not Thru Paint



5: Door nsr Chipped 1 To 5



7: Qtr Panel nsr Scratched UpTo 25mm Thru Paint



4: Door nsf Scratched UpTo 25mm Thru Paint



6: Wheel nsr Scratched Over 50mm



8: Bumper Rear Scratched 25 to 100mm Thru Paint



9: Boot Lid Scratched UpTo 25mm Thru Paint



10: Qtr Panel osr Scratched UpTo 25mm Thru Paint



11: Door osr Scratched UpTo 25mm Thru Paint



12: Door osf Chipped Edge Chip



13: Wheel osf Scratched Over 50mm



14: Bonnet Chipped 1 To 5

#### Interior

**Carpet Condition Seat Condition** 

Average Average **Upholstery Condition Odour** 

Average No

## **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake OK		Gearbox Static Gear Selection (engine running)	
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated OK		DPF light illuminated	
ABS light illuminated OK		Service indicator light illuminated	
Windows	OK	Radio	OK
Sat nav OK		Steering	OK