



VEHICLE INSPECTION REPORT

MT21DSZ

Vauxhall Movano 2.3 Turbo D 135ps H2 Van

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

nama
GRADE
4

Details

Reg. date 31/03/2021

Colour WHITE

MOT Due 29/05/2026

Year 2021

VIN W0VMR8608MB252771

Gearbox MANUAL

Mileage 42,168 Miles
Warranted

Body Style Panel Van

Gears 6

Fuel Type Diesel

Keys 1

It appears that the vehicle may have had an engine replacement, as several indicators suggest it is not the original factory-fitted unit. Specifically:

- The engine number does not match the vehicle identification records.
- The wiring loom and pipework appear to be damaged, incorrectly routed, and non-original.
- The overall installation does not appear consistent with standard Vauxhall manufacturing or service procedures.

In addition, a diagnostic review of the vehicle's electronic control unit (ECU) indicates that software modifications have been carried out. These include:

- AdBlue, DPF, and EGR delete functions removed from the ECU.
- Evidence of non-standard programming or tuning.

Heavy vibration at idle It appears that the vehicle may have had an engine replacement, as several indicators suggest it is not the original factory-fitted unit. Specifically:

- The engine number does not match the vehicle identification records.
- The wiring loom and pipework appear to be damaged, incorrectly routed, and non-original.
- The overall installation does not appear consistent with standard Vauxhall manufacturing or service procedures.

In addition, a diagnostic review of the vehicle's electronic control unit (ECU) indicates that software modifications have been carried out. These include:

- AdBlue, DPF, and EGR delete functions removed from the ECU.
- Evidence of non-standard programming or tuning.

Heavy vibration at idle

Tyres

NSF HANKOOK 5.0mm

NSR BUDGET Worn

OSF HANKOOK 4.0mm

OSR FARROAD 5.0mm

Spare


Features

- Bluetooth connection
- Cruise control
- Navigation system
- Digital radio
- Air conditioning
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos



Condition Check



Damage Photos



1: Other
N/A
N/A



2: Other
N/A
N/A



3: Bonnet
Chipped
Multiple Chips



4: Wing nsf
Chipped
Multiple Chips



5: Door nsf
Chipped
1 To 5



6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Hole
Over 10mm



8: Qtr Panel nsr
Dented
Over 30mm



9: Boot Lid
Dented
Over 30mm




10: Bumper Rear Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Qtr Panel osr
Dented
Over 30mm




12: Door osf
Chipped
1 To 5



13: Door osf
Scratched
Over 25mm Not Thru Paint



14: Wing osf
Dented
Over 30mm



15: Screen Front
Chipped
UpTo 10mm

16: Roof
Dented
Over 30mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK