



VEHICLE INSPECTION REPORT

GK22EHS

Nissan Qashqai 1.3 DiG-T MH 158 Tekna+ 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	23/06/2022	Body Style	Hatchback	MOT Due	Expired
Year	2022	Keys	2	Gearbox	MANUAL
Mileage	18,545 Miles Warranted	Service history	Yes	Gears	6
Fuel Type	Hybrid Electric	Service documents	Printout	Doors	5
Colour	BLUE	Last service date	29/05/2024		
VIN	SJNTAAJ12U1118476	Last service miles	12,867		

£65 ADDITIONAL FEE Last service 29/05/2024 @ 12867 miles (2 MAIN DEALER SERVICES)

Tyres

NSF	MICHELIN	2.0mm
NSR	CONTINENTAL	5.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	4.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Audio remote control
- Electric door mirrors
- Climate control
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Electrically adjustable drivers seat
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Leather seat trim
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Front parking sensor
- PAS
- Telephone
- Digital radio
- LED headlights
- Electrically adjustable passenger seat
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bumper Rear
Scratched
25 to 100mm Thru Paint



2: Wheel nsr
Scratched
Over 50mm

No Image

3: Door nsr
Scratched
Over 25mm Not Thru Paint

No Image

4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Wheel nsf
Scratched
Over 50mm

No Image

6: Bonnet
Scratched
Over 25mm Not Thru Paint



7: Bumper Front
Chipped
Multiple Chips



8: Wheel osf
Scratched
Up To 50mm

No Image



9: Door osr
Scratched
Over 25mm Not Thru Paint

10: Wheel osr
Scratched
Over 50mm



11: Door nsr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK