



VEHICLE INSPECTION REPORT

PK15OSZ

Volkswagen Tiguan 2.0 TDi BlueMotion Tech Match 177 5dr DSG

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	30/04/2015	VIN	WVGZZZ5NZFW099397	Last service date	19/06/2025
Year	2015	Body Style	Estate	Last service miles	109,500
Mileage	112,513 Miles Warranted	Service history	Yes	MOT Due	29/10/2026
Fuel Type	Diesel	Service documents	Service Book	Gearbox	SEMI AUTO
Colour	BLUE	Number of stamps	9	Gears	7

£65 ADDITIONAL FEE. Last service 19/06/2025 at 109500 miles (9 services (5 main dealer). Book & print.

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- PAS
- Digital radio
- Opening panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Remote central locking
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Poor Paint



2: Bumper Front
Poor Previous Repair
Poor Paint



3: Fogdriving Lamp nsf
Broken
Replace



4: Wing nsf
Dented
With Paint Damage



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
Multiple Chips



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



12: Door osr
Scratched
Over 25mm Thru Paint



13: Door osf
Dented
With Paint Damage



14: Wing osf
Poor Previous Repair
Poor Paint



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-

Vehicle Inspection Report

Disclaimer
 Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
 Additional fees may apply to some vendors.
 Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		