



VEHICLE INSPECTION REPORT

GX21YZK

Seat Ibiza 1.0 TSI 110 FR [EZ] 5dr

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	Present



Details

Reg. date	09/04/2021	Body Style	Hatchback	Last service miles	23,726
Year	2021	Keys	2	MOT Due	08/04/2026
Mileage	47,218 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	WHITE	Number of stamps	1	Doors	5
VIN	VSSZZZKJZMR058689	Last service date	28/09/2023		

£65 ADDITIONAL FEE. Last service 28/09/2023 at 23726 miles (1 main dealer service). Noise from engine after revving

Tyres

NSF	BUDGET	2.0mm
NSR	LAUFENN	3.0mm
OSF	LAUFENN	2.0mm
OSR	LAUFENN	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Digital radio
- Climate control
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Between 10mm + 30mm



5: Door nsf
Dented
Over 2 UpTo 10mm



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Chipped
1 To 5



8: Wheel nsr
Scratched
Up To 50mm



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Dented
Over 2 UpTo 10mm



12: Qtr Panel osr
Dented
With Paint Damage



13: Qtr Panel osr
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: A Post os
Dented
Over 30mm



16: Door osf
Dented
Over 2 UpTo 10mm



17: Door osf
Scratched
Over 25mm Not Thru Paint



18: Wing osf
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Sill os
Dented
Over 30mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK