



# VEHICLE INSPECTION REPORT

**GX63PYT**

## Mercedes-Benz A Class A200 CDI BlueEFFICIENCY AMG Sport 5dr Auto

Inspection		Vehicle	
Serious Damage?	No	VAT	Margin
		V5	TBC



### Details

Reg. date	19/09/2013	VIN	WDD1760012J110633	CAP Average	£5,800.00
Year	2013	Body Style	Hatchback	CAP Below	£4,950.00
Mileage	72,389 Miles Warranted	Keys	3	Doors	5
Fuel Type	Diesel	MOT Due	18/09/2025		
Colour	WHITE	CAP Clean	£6,650.00		

£65 ADDITIONAL FEE.

### Tyres

NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	3.0mm
OSF	CONTINENTAL	4.0mm
OSR	CONTINENTAL	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear parking sensor
- Trip computer
- Body coloured bumpers
- Climate control
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Cruise control
- Rear wiper
- Audio remote control
- Electric door mirrors
- Front electric windows
- Rear electric windows
- ABS
- Central locking
- Front parking sensor
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front head restraints
- Rear headrests
- Drivers airbag
- Remote central locking
- PAS
- Telephone
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Solid Paint
- Isofix child seat anchor points
- Leather seat trim

## Photos






## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
UpTo 10mm



2: Bonnet  
Chipped  
1 To 5





3: Bumper Front  
Chipped  
Multiple Chips




4: Wheel nsf  
Scratched  
Over 50mm




5: Wing nsf  
Dented  
Over 30mm



6: Wheel nsr  
Scratched  
Over 50mm




7: Door nsf  
Scratched  
Over 25mm Not Thru Paint



8: Door nsr  
Scratched  
Over 25mm Not Thru Paint



9: Bumper Rear  
Dented  
Over 30mm




10: Boot Lid  
Scratched  
Over 25mm Not Thru Paint




11: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm



12: Wheel osr  
Scratched  
Over 50mm



13: Door osr  
Scratched  
Over 25mm Not Thru Paint



14: Door osf  
Scratched  
Over 25mm Not Thru Paint



15: Wheel osf  
Scratched  
Over 50mm



16: Boot Lid  
Dented  
Over 30mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK