

#### 46 Brampton Road Eastbourne **BN22 9BN** 01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**NRZ2153** 

## Mercedes-Benz C Class C200d AMG Line 4dr Auto

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		8 3 S
		V5	TBC		
Details					
Reg. date	28/11/2017	VIN	WDD2050372R273544	CAP Average	£9,100.00
Year	2017	Body Style	Saloon	CAP Below	£8,050.00
Mileage	63,706 Miles Warranted	Keys	2	Doors	4
		MOT Due	15/08/2025		
Fuel Type	Diesel	CAP Clean	£10,150.00		
Colour	GREY		,		

#### £65 ADDITIONAL FEE.

Tyres			
NSF	BUDGET	4.0mm	
NSR	WESTLAKE	3.0mm	
OSF	PIRELLI	3.0mm	
OSR	WESTLAKE	4.0mm	
Spare			

## **Features**

- Bluetooth connection
- Park assist camera
- Telephone
- Digital radio Heated door mirrors
- Electrically adjustable passenger •
- seat
- Height adjustable drivers seatMetallic Paint
- Isofix child seat anchor points
- · Leather seat trim
- Front armrest

PAS

٠

Rear armrest •

Air conditioning

Cruise control

3x3 point rear seat belts ٠

Trip computer Body coloured bumpers

- Passenger airbag
- Alloy wheels

- Front parking sensor Rear parking sensor •
- Audio remote control . Electric door mirrors •
- Climate control •
- Front electric windows
- · Rear electric windows
- ABS
- · Central locking

- Navigation systemSteering wheel mounted controls
- Auxiliary input socket Front fog lights
- Electrically adjustable drivers seat
  Front head restraints
- · Rear headrests
- Drivers airbag
  Remote central locking

### **Photos**






















## **Condition Check**



## Damage Photos





1: Boot Lid Scratched Over 25mm Thru Paint

2: Bumper Rear Scratched 25 to 100mm Thru Paint

# No Image

3: Bumper Rear Scratched Over 25mm Not Thru Paint





4: Qtr Panel nsr Chipped 1 To 5

# No Image

6: Door nsr Scratched Over 25mm Not Thru Paint



7: Door nsf Chipped 1 To 5

Scratched

Over 50mm



8: Wheel nsf Scratched Over 50mm







11: Wing osf Chipped 1 To 5



10: Bumper Front Scratched 25 to 100mm Thru Paint



12: Wheel osf Scratched Over 50mm



13: Screen Front Chipped UpTo 10mm




14: Door osf Chipped 1 To 5





15: Door osr Chipped 1 To 5



17: Wheel osr Scratched Over 50mm

Interior

Carpet Condition Seat Condition Average Average Upholstery Condition Odour

Scratched

Average No

### **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors. Please note buyers rate increase from 01/01/2025

Engine Runs OK	Gearbox 1st and Reverse Test OK
Brakes OK	Clutch Slip Test from Static OK
Turbo Boosting OK	Gearbox Static Gear Selection (engine running) OK
Parking Brake OK	No Excessive Smoking OK

EML light illuminated OK	Oil warning light illuminated OK
Airbag light illuminated OK	DPF light illuminated OK
ABS light illuminated OK	Service indicator light illuminated OK
Windows	Radio OK
	RadioOKSteeringOK