

## **VEHICLE INSPECTION REPORT**



## Skoda Octavia 1.6 TDI CR SE 5dr DSG

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 Grade
		V5	TBC		
Details					
Reg. date	26/04/2019	VIN	TMBBG7NE9K0104216	CAP Average	£4,525.00
Year	2019	Body Style	Hatchback	CAP Below	£3,875.00
Mileage	110,442 Miles	Keys	2	Gearbox	SEMI AUTO
	Warranted	MOT Due	27/03/2026	Gears	7
Fuel Type	Diesel	CAP Clean	£5,225.00	Doors	5
Colour	GREY			-	

#### £100 ADDITIONAL FEE. Engine noisy

-				
ı	У	r	е	s


NSF	GOODYEAR	2.0mm
NSR	KUMHO	4.0mm
OSF	GOODYEAR	3.0mm
OSR	KUMHO	4.0mm
Spare		

## **Features**

- Bluetooth connection
- PASTelephone
- Digital radio Climate control
- Rear electric windows
- ABS
- Traction controlAlloy wheels


- · Cruise control
- Rear parking sensor
- Trip computer Body coloured bumpers
- Front electric windows
- Rear headrests
- Drivers airbagCentral locking
- Front parking sensor
- Rear wiperAudio remote control
- · Electric door mirrors
- Front head restraints
- Metallic Paint
- Passenger airbagRemote central locking
- Park assist camera
- Park assist camera
  Steering wheel mounted controls
  Auxiliary input socket
  Air conditioning
  Height adjustable drivers seat
  3x3 point rear seat belts
  Side airbags
  Leather seat trim

## **Photos**










## **Condition Check**



## **Damage Photos**



1: Door Pad osf Scuffed UpTo 25mm



2: Bonnet Chipped 1 To 5



3: Bumper Front Chipped Multiple Chips



4: Wheel nsf Scratched Over 50mm



5: Door nsr Scratched Over 25mm Thru Paint



6: Door nsr Chipped 1 To 5



7: Qtr Panel nsr Chipped 1 To 5



8: Wheel nsr Corroded Light



9: Bumper Rear Scratched 25 to 100mm Thru Paint



10: Qtr Panel osr Dented Between 10mm + 30mm



11: Wheel osr Scratched Over 50mm



12: Door osr Chipped 1 To 5



13: Door osf Dented Over 2 UpTo 10mm



14: Wheel osf Corroded Light



### 15: D Post ns Dented Over 2 UpTo 10mm

# No Image

16: D Post os Dented 2 Or Less UpTo 10mm

#### Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

## **Vehicle Inspection Report**

#### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK