

VEHICLE INSPECTION REPORT

GY72VLG

Dacia Duster 1.0 TCe 90 Comfort 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	09/11/2022
Year	2022
Mileage	38,831 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	VF1HJD20769793045

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	3
Last service date	27/12/2025

Last service miles	38,043
MOT Due	08/11/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE

Last service 27/12/2025 at 38,043 miles- 3 main dealer services

Tyres

NSF	NEXEN	4.0mm
NSR	NEXEN	4.0mm
OSF	NEXEN	4.0mm
OSR	NEXEN	4.0mm
Spare		

Features


- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsr
Dented
2 Or Less UpTo 10mm

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Dented
With Paint Damage



11: Wheel nsr
Scratched
Up To 50mm



12: Bumper Rear
Chipped
Multiple Chips



13: Bumper Rear
Scratched
Over 25mm Not Thru Paint


14: Boot Lid
Dented
Over 2 UpTo 10mm




15: Qtr Panel osr
Dented
Between 10mm + 30mm



16: Wheel osr
Scratched
Up To 50mm



17: Door osr
Dented
Over 2 UpTo 10mm



18: Door osf
Dented
Over 30mm



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK