

VEHICLE INSPECTION REPORT

PX63FHB

Ford C-Max 1.6 Zetec 5dr

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	30/09/2013	Body Style	MPV	Last service miles	99,207
Year	2013	Keys	2	MOT Due	Expired
Mileage	119,139 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BROWN	Number of stamps	11		
VIN	WF0JXXWPBJDC27857	Last service date	13/07/2023		

Last service 13/07/2023 at 99,207 miles- 11 services (4 main dealer)

MOT EXPIRED Exhaust blowing and airbag light on

Car has been plugged in for airbag light and detects centre frontal restraints sensor (subfault) no operation

Tyres



NSF	HANKOOK	3.0mm
NSR	RAPID	4.0mm
OSF	HANKOOK	3.0mm
OSR	BUDGET	4.0mm
Spare		

Features


• Bluetooth connection	• PAS	• Rear wiper	• Steering wheel mounted controls
• Audio remote control	• Radio/CD	• Body coloured bumpers	• Electric door mirrors
• Air conditioning	• Climate control	• Front armrest	• Front electric windows
• Front head restraints	• Height adjustable drivers seat	• Rear headrests	• Metallic Paint
• 3x3 point rear seat belts	• ABS	• Drivers airbag	• Isofix child seat anchor points
• Passenger airbag	• Side airbags	• Traction control	• Central locking
• Remote central locking	• Cloth seat trim	• Alloy wheels	

Photos





Condition Check



Damage Photos



1: Bumper Rear
Dented
With Paint Damage



2: Boot Lid
Dented
With Paint Damage



3: Qtr Panel osr
Dented
With Paint Damage



4: Wheel osr
Scratched
Over 50mm



5: Door osr
Dented
With Paint Damage



6: Door osf
Dented
With Paint Damage



7: Wing osf
Dented
Over 30mm



8: Wheel osf
Scratched
Over 50mm



9: Bonnet
Dented
With Paint Damage



10: Bumper Front
Cracked
Over 25mm



11: Wing nsf
Dented
With Paint Damage



12: Wheel nsf
Scratched
Over 50mm



13: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



14: Door nsf
Chipped
Multiple Chips



15: Door nsr
Dented
With Paint Damage



16: Qtr Panel nsr
Dented
With Paint Damage



17: Wheel nsr
Scratched
Over 50mm



18: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK