

VEHICLE INSPECTION REPORT

HN62YDY

Ford Focus 1.6 125 Zetec 5dr Powershift

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 3

Details

Reg. date	24/12/2012
Year	2012
Mileage	73,508 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	WF0LXXGCBLC21085

Body Style	Estate	Last service miles	66,478
Keys	2	MOT Due	01/11/2026
Service history	Yes	Gearbox	AUTOMATIC
Service documents	Service Book	Gears	6
Number of stamps	9		
Last service date	21/06/2024		

Last Service - 21.06.2024 at 66478 miles (9 services) Gearbox fault on dash

Tyres


NSF	BUDGET	4.0mm
NSR	BUDGET	2.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


• Bluetooth connection	• PAS	• Rear wiper	• Steering wheel mounted controls
• Audio remote control	• Radio/CD	• Body coloured bumpers	• Electric door mirrors
• Air conditioning	• Climate control	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear headrests	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag
• Side airbags	• Traction control	• Central locking	• Remote central locking
• Cloth seat trim	• Alloy wheels		

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Chipped
Multiple Chips



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Over 2 UpTo 10mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsr
Dented
Over 30mm




8: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image

9: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Chipped
1 To 5



14: D Post ns
Dented
Over 2 UpTo 10mm



15: Qtr Panel osr
Chipped
1 To 5

No Image

16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Scratched
Over 50mm




18: Door osr
Dented
2 Or Less UpTo 10mm



19: Door osf
Chipped
1 To 5



20: Wing osf
Chipped
1 To 5



21: Screen Front
Chipped
UpTo 10mm



22: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK