

## VEHICLE INSPECTION REPORT

BP73POV

### Lexus RX 450h+ 2.5 5dr E-CVT [Premium Plus Pack]

Inspection	Vehicle	nama GRADE 2
Serious Damage?	VAT	Margin
No	V5	Present

#### Details

Reg. date	21/12/2023	VIN	JTJCJBGA802007395	Number of stamps	2
Year	2023	Body Style	Estate	Last service date	19/05/2025
Mileage	23,895 Miles Warranted	Keys	2	Last service miles	20,223
Fuel Type	Hybrid Electric	Service history	Yes	Gearbox	CVT
Colour	BLUE	Service documents	Service Book	Gears	1

#### £65 ADDITIONAL FEE

Last service 19/05/2025 at 20,223 miles- 2 main dealer services. Book Type 2 and 3 pin cables in boot

#### Tyres




NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	4.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

## Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Electrically adjustable drivers seat
- Height adjustable drivers seat
- Metallic Paint
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear armrest
- Central locking
- Front parking sensor
- PAS
- Audio remote control
- Air conditioning
- Front electric windows
- Rear electric windows
- Remote central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Front head restraints
- Rear headrests
- Leather seat trim

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips

No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint




5: Wheel nsf  
Scratched  
Up To 50mm

No Image

7: Door nsr  
Scratched  
Over 25mm Not Thru Paint

No Image

4: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



6: Door nsf  
Chipped  
1 To 5


No Image

8: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



9: Bumper Rear  
Chipped  
Multiple Chips

No Image



11: Door osr  
Scratched  
UpTo 25mm Thru Paint

10: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint

No Image



13: Door osf  
Chipped  
1 To 5

12: Door osr  
Scratched  
Over 25mm Not Thru Paint

No Image

14: Door osf  
Scratched  
Over 25mm Not Thru Paint

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK