



VEHICLE INSPECTION REPORT

GV16NXH

Toyota Auris 1.8 Hybrid Excel 5dr CVT

| Inspection | | Vehicle | |
|-----------------|----|---------|--------|
| Serious Damage? | No | VAT | Margin |
| | | V5 | TBC |



Details

| | | | | | |
|-----------|---------------------------|------------|-------------------|-------------|-----------|
| Reg. date | 25/06/2016 | VIN | SB1ZS3JE60E235247 | CAP Average | £7,525.00 |
| Year | 2016 | Body Style | Estate | CAP Below | £6,550.00 |
| Mileage | 68,863 Miles Warranted | Keys | 2 | Gearbox | CVT |
| Fuel Type | Hybrid Electric | MOT Due | 05/06/2025 | Gears | 1 |
| Colour | BLUE | CAP Clean | £8,500.00 | | |

£65 ADDITIONAL FEE Rear bumper misaligned

Tyres


| | | |
|-------|--------|-------|
| NSF | BUDGET | 4.0mm |
| NSR | BUDGET | 4.0mm |
| OSF | BUDGET | 4.0mm |
| OSR | BUDGET | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Rear wiper
- Audio remote control
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Steering wheel mounted controls
- Auxiliary input socket
- Front fog lights
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels
- Park assist camera
- Telephone
- Digital radio
- Heated door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- PAS
- Trip computer
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Dented
With Paint Damage




3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Dented
Over 30mm



5: Door nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsr
Scratched
Over 25mm Not Thru Paint



7: Qtr Panel nsr
Chipped
Multiple Chips



8: Bumper Rear
Poor Previous Repair
Rippled Over 30%



9: Qtr Panel osr
Dented
With Paint Damage



10: Wheel nsr
Scratched
Up To 50mm



11: Wheel osr
Corroded
Light



12: Door osr
Chipped
1 To 5



13: Door osf
Chipped
1 To 5



14: Wheel osf
Scratched
Over 50mm

No Image

15: Bonnet
Dented
Over 2 UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|--------------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| | | Clutch Slip Test from Static | OK |
| | | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |