

VEHICLE INSPECTION REPORT

RV09BZP

BMW 3 Series 318i ES 4dr

Inspection

Serious Damage? No

Vehicle

VAT

V5 TBC

nama
GRADE 5

Details

Reg. date	09/03/2009
Year	2009
Mileage	125,388 Miles Warranted
Fuel Type	Petrol

Colour	SILVER
VIN	WBAPF52040A501259
Body Style	Saloon
Keys	2

MOT Due	15/11/2026
Gearbox	MANUAL
Gears	6
Doors	4

Service due display

Tyres

NSF	BUDGET	Damaged
NSR	LAUFENN	4.0mm
OSF	JOYROAD	Damaged
OSR	FALKEN	4.0mm
Spare		

Features


- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Passenger airbag
- Remote central locking
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Rear airbags
- Cloth seat trim
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- ESP
- Side airbags
- Alloy wheels
- Radio/CD
- Towbar
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Isofix child seat anchor points
- Central locking

Photos






Condition Check



Damage Photos



1: Seat Back Cover osf
Holed
Over 3mm



2: Door Pad osf
Scuffed
Over 25mm




3: Door Pad nsf
Scuffed
Over 25mm



4: Bonnet
Chipped
Multiple Chips




5: Bumper Front
Scratched
Over 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: Wing nsf
Chipped
1 To 5



8: A Post nsf
Scratched
Over 25mm Thru Paint



9: Door nsf
Poor Previous Repair
Poor Paint



10: Door nsr
Dented
With Paint Damage



11: Aperture Seal nsr
Broken
Replace



12: Wheel nsr
Scratched
Over 50mm



13: Qtr Panel nsr
Dented
With Paint Damage



14: Bumper Rear
Scratched
Over 100mm Thru Paint



15: Qtr Panel osr
Dented
Over 30mm



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Over 30mm



18: Door osf
Dented
With Paint Damage



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Scratched
Over 25mm Thru Paint



21: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



22: Tyre osf
Damaged
Replace



23: Tyre nsf
Damaged
Replace

Interior

Carpet Condition Average
Seat Condition Poor

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK