

VEHICLE INSPECTION REPORT

YK67WBZ

Toyota Yaris 1.5 Hybrid Icon 5dr CVT

| Inspection | | Vehicle | | | nama |
|-----------------|---------------------------|------------|---------------------------------------|-------------|-----------|
| Serious Damage? | No | VAT | Margin | | 2 GRADE |
| | | V5 | TBC | | |
| Details | | | | | |
| Reg. date | 04/01/2018 | VIN | VNKKD3D380A397316 | CAP Average | £9,375.00 |
| Year | 2018 | Body Style | Hatchback | CAP Below | £8,300.00 |
| Mileage | 11,534 Miles Warranted | Keys | 2 | Gearbox | CVT |
| | | MOT Due | 20/11/2025 | Gears | 1 |
| Fuel Type | Hybrid Electric | CAP Clean | £10,450.00 | Doors | 5 |
| Colour | WHITE | | · · · · · · · · · · · · · · · · · · · | | |

£65 ADDITIONAL FEE

| _ | | | |
|---|---|---|---|
| У | r | е | S |

| NSF | CONTINENTAL | 4.0mm |
|-------|-------------|-------|
| NSR | DUNLOP | 5.0mm |
| OSF | DUNLOP | 4.0mm |
| OSR | FALKEN | 4.0mm |
| Spare | | |

Features

- Bluetooth connection
- Rear wiper
- Audio remote control
 Electric door mirrors
- · Front head restraints
- ABS
- Traction controlAlloy wheels

- Cruise control
- Steering wheel mounted controls

 Auxiliary input socket
 Air conditioning

 Telephone
 Digital radio
 Climate cor

- Rear headrests
- Drivers airbagCentral locking
- · Park assist camera
- Digital radio
- Climate control
- Solid Paint
- Isofix child seat anchor pointsRemote central locking

- Trip computer
 Body coloured bumpers
 Front electric windows
 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos
























Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Scratched 25 to 100mm Thru Paint

No Image

3: Wing nsf Scratched Over 25mm Not Thru Paint



4: Wheel nsf Scratched Over 50mm

No Image

5: Door nsf Scratched Over 25mm Not Thru Paint



7: Wheel nsr Scratched Up To 50mm

No Image

6: Door nsr Scratched Over 25mm Not Thru Paint



8: Bumper Rear Scratched 25 to 100mm Thru Paint

No Image

No Image

9: Qtr Panel osr Scratched Over 25mm Not Thru Paint 10: Door osrScratchedOver 25mm Not Thru Paint

No Image

11: Door osfScratchedOver 25mm Not Thru Paint



12: Wheel osr Scratched Over 50mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| Engine Runs OK | Gearbox 1st and Reverse Test OK |
|-------------------|---|
| Brakes OK | Clutch Slip Test from Static OK |
| Turbo Boosting OK | Gearbox Static Gear Selection (engine running) OK |
| Parking Brake OK | No Excessive Smoking OK |

| EML light illuminated | OK | Oil warning light illuminated | OK |
|--------------------------|----|-------------------------------------|----|
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |