

## VEHICLE INSPECTION REPORT

YE17XVD

### Lexus CT 200h 1.8 Advance 5dr CVT Auto

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE  
3

#### Details

Reg. date	28/04/2017
Year	2017
Mileage	43,023 Miles Warranted
Fuel Type	Hybrid Electric
Colour	BLACK
VIN	JTHKD5BH002300685

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	7
Last service date	28/10/2025

Last service miles	42,445
MOT Due	24/06/2026
Gearbox	CVT
Gears	1
Doors	5

#### £100 ADDITIONAL FEE

Last service 28/10/2025 at 42,445 miles- 7 services (3 main dealer) Book and print

#### Tyres

NSF	GOODYEAR	4.0mm
NSR	BRIDGESTONE	5.0mm
OSF	GOODYEAR	5.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Park assist camera
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Navigation system
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Curtain airbags
- Traction control
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Chipped  
Multiple Chips

# No Image

3: Bumper Front  
Scratched  
Over 25mm Not Thru Paint



4: Wheel nsf  
Scratched  
Over 50mm



5: Wing nsf  
Chipped  
1 To 5

# No Image

6: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



7: Door Mirror Assy nsf  
Scratched (Painted)  
UpTo 25mm Thru Paint



8: Door nsf  
Scratched  
Over 25mm Thru Paint



9: Door nsr  
Dented  
2 Or Less UpTo 10mm

No Image

10: Door nsr  
Scratched  
Over 25mm Not Thru Paint



11: Qtr Panel nsr  
Chipped  
1 To 5




12: Wheel nsr  
Scratched  
Over 50mm



13: Bumper Rear  
Scratched  
Over 100mm Thru Paint



14: Boot Lid  
Chipped  
1 To 5



15: Qtr Panel osr  
Poor Previous Repair  
Poor Paint



16: Wheel osr  
Scratched  
Over 50mm



17: Door osr  
Chipped  
1 To 5

No Image

18: Door osr  
Scratched  
Over 25mm Not Thru Paint



19: Door osf  
Chipped  
1 To 5

No Image

20: Door osf  
Scratched  
Over 25mm Not Thru Paint



21: Wing osf  
Chipped  
1 To 5



22: Wheel osf  
Scratched  
Over 50mm



23: Screen Front  
Chipped  
UpTo 10mm

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK