

# VEHICLE INSPECTION REPORT

**MJ13JZL**

## Nissan Juke 1.6 Tekna 5dr CVT

### Inspection

**Serious Damage?** No

### Vehicle

<b>VAT</b>	Margin
<b>V5</b>	Present

nama  
GRADE 3

### Details

<b>Reg. date</b>	25/05/2013
<b>Year</b>	2013
<b>Mileage</b>	87,398 Miles Warranted
<b>Fuel Type</b>	Petrol
<b>Colour</b>	WHITE

<b>VIN</b>	SJNFBASF15U6390626
<b>Body Style</b>	Hatchback
<b>Keys</b>	2
<b>Service history</b>	None
<b>MOT Due</b>	24/06/2026

<b>Gearbox</b>	CVT
<b>Gears</b>	1
<b>Doors</b>	5

No service history Gearbox fault

Car judders when pulling away and revs bounce when up to speed

### Tyres


<b>NSF</b>	RAPID	5.0mm
<b>NSR</b>	RAPID	5.0mm
<b>OSF</b>	RAPID	5.0mm
<b>OSR</b>	RAPID	5.0mm
<b>Spare</b>		

## Features


<ul style="list-style-type: none"> <li>Bluetooth connection</li> <li>Park assist camera</li> <li>Digital radio</li> <li>Air conditioning</li> <li>Front head restraints</li> <li>Steering wheel rake adjustment</li> <li>ABS</li> <li>Passenger airbag</li> <li>Leather seat trim</li> </ul>	<ul style="list-style-type: none"> <li>Cruise control</li> <li>PAS</li> <li>Body coloured bumpers</li> <li>Folding rear seats</li> <li>Height adjustable drivers seat</li> <li>Steering wheel reach adjustment</li> <li>Drivers airbag</li> <li>Side airbags</li> <li>Alloy wheels</li> </ul>	<ul style="list-style-type: none"> <li>Heated front seat</li> <li>Rear wiper</li> <li>Electric door mirrors</li> <li>Front armrest</li> <li>Rear electric windows</li> <li>Metallic Paint</li> <li>ESP</li> <li>Central locking</li> </ul>	<ul style="list-style-type: none"> <li>Navigation system</li> <li>Steering wheel mounted controls</li> <li>Front fog lights</li> <li>Front electric windows</li> <li>Rear headrests</li> <li>3x3 point rear seat belts</li> <li>Isofix child seat anchor points</li> <li>Remote central locking</li> </ul>
--	---	--	--

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
1 To 5



2: Bumper Front  
Scratched  
UpTo 25mm Thru Paint



3: Wheel nsf  
Corroded  
Light



4: Wing nsf  
Chipped  
1 To 5



5: Roof  
Dented  
With Paint Damage



6: Handle Outer nsf  
Scratched (Painted)  
Over 25mm Thru Paint



7: Door nsf  
Chipped  
1 To 5



8: Door nsr  
Dented  
Between 10mm + 30mm




9: Door nsr  
Scratched  
UpTo 25mm Thru Paint



10: Wheel nsr  
Scratched  
Over 50mm



11: Bumper Rear  
Scratched  
25 to 100mm Thru Paint



13: Wheel osr  
Corroded  
Light



14: Door osr  
Scratched  
UpTo 25mm Thru Paint



15: Door osf  
Chipped  
Edge Chip



16: Wheel osf  
Scratched  
Over 50mm



17: Wing osf  
Chipped  
1 To 5

## Interior

**Carpet Condition** Average  
**Seat Condition** Average

**Upholstery Condition** Average  
**Odour** No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK