

VEHICLE INSPECTION REPORT

FV14OOY

Mini Hatchback 1.5 Cooper 3dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE
2

Details

Reg. date	18/06/2014
Year	2014
Mileage	109,408 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	WMWXM52070T945035

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	08/04/2022

Last service miles	66,464
MOT Due	09/08/2026
Gearbox	MANUAL
Gears	6
Doors	3

Last service 08/04/2022 at 66464 miles (3 services (4 main dealer)).

Tyres



NSF	BUDGET	3.0mm
NSR	TOYO	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	3.0mm
Spare		

Features


- Bluetooth connection
- Steering wheel mounted controls
- Air conditioning
- Height adjustable drivers seat
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- Audio remote control
- Climate control
- Rear headrests
- Isofix child seat anchor points
- Central locking
- PAS
- Body coloured bumpers
- Front electric windows
- Solid Paint
- Passenger airbag
- Remote central locking
- Rear wiper
- Electric door mirrors
- Front head restraints
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5




2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Chipped
1 To 5



7: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

4: Wheel nsf
Scratched
Up To 50mm

No Image

6: Door nsf
Scratched
Over 25mm Not Thru Paint

No Image

8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm




10: Bumper Rear
Poor Previous Repair
Poor Paint



11: Boot Lid
Dented
Over 2 UpTo 10mm



12: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



13: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



14: Wheel osr
Scratched
Up To 50mm



15: Door osf
Dented
Over 2 UpTo 10mm

No Image

16: Door osf
Scratched
Over 25mm Not Thru Paint



17: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK