

# VEHICLE INSPECTION REPORT

FE05WCV

## Mini Hatchback 1.6 One 3dr

### Inspection

Serious Damage? No

### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

### Details

Reg. date	01/03/2005
Year	2005
Mileage	83,595 Miles Warranted
Fuel Type	Petrol

Colour	BLUE
VIN	WMWRA320X0TK08580
Body Style	Hatchback
Keys	2

MOT Due	29/03/2026
Gearbox	MANUAL
Gears	5
Doors	3

Car knocking while driving  
Gear stick Stiff

### Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	3.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm


Spare

## Features


- PAS
- Body coloured bumpers
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Service indicator
- Opening panoramic glass roof
- Height adjustable drivers seat
- Metallic Paint
- ESP
- Central locking
- Radio/CD
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking

## Photos





## Condition Check



## Damage Photos



1: Bumper Rear  
Poor Previous Repair  
Poor Paint




2: Boot Lid  
Dented  
Over 30mm



3: Roof  
Poor Previous Repair  
Poor Paint



4: Qtr Panel osr  
Dented  
2 Or Less UpTo 10mm




5: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



6: Wheel osr  
Scratched  
Over 50mm



7: Door osf  
Dented  
Over 2 UpTo 10mm



8: Door osf  
Scratched  
Over 25mm Not Thru Paint



9: Door osf  
Chipped  
Edge Chip



10: Wing osf  
Chipped  
1 To 5




11: Screen Front  
Chipped  
UpTo 10mm



12: Wheel osf  
Scratched  
Over 50mm



13: Bonnet  
Scratched  
Over 25mm Thru Paint




14: Bumper Front  
Poor Previous Repair  
Paint Flake



15: Wheel nsf  
Scratched  
Over 50mm




16: Door nsf  
Dented  
Over 2 UpTo 10mm



17: Door nsf  
Scratched  
Over 25mm Not Thru Paint



18: Qtr Panel nsr  
Dented  
Over 2 UpTo 10mm



19: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



20: Wheel nsr  
Scratched  
Over 50mm

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK