

VEHICLE INSPECTION REPORT

HY65OMG

Volkswagen Tiguan 2.0 TDi BlueMotion Tech R-Line 5dr 150 DSG [NAV]

Inspection		Vehicle			nama
Serious Damage?	No	VAT	Margin		2 GRADE
		V5	Present		
Details					
Reg. date	01/09/2015	Body Style	Estate	Last service miles	81,265
Year	2015	Keys	2	MOT Due	07/07/2026
Mileage	84,671 Miles Warranted	Service history	Yes	Gearbox	SEMI AUTO
Fuel Type	Diesel	Service documents	Service Book	Gears	7
Colour	WHITE	Number of stamps	10		
VIN	WVGZZZ5NZGW018818	Last service date	28/06/2025	_	

£65 ADDITIONAL FEE. Last service 28/06/2025 at 81265 miles (10 services (3 main dealer).

_	-			
	1/	r	0	c
	v		┖	-

NSF	MICHELIN	4.0mm	
NSR	MICHELIN	4.0mm	
OSF	MICHELIN	4.0mm	
OSR	MICHELIN	4.0mm	
Spare			

Features

- Bluetooth connection
- Steering wheel mounted controls Audio remote control
- Electric door mirrors
- · Front electric windows
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels


- Navigation system
- Air conditioning Front head restraints
- Solid Paint
- Isofix child seat anchor points
- Central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- · Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Side airbags
- Cloth seat trim

Photos











Condition Check



Damage Photos



1: Bonnet Chipped 1 To 5



2: Bumper Front Poor Previous Repair Poor Paint



3: Wing nsf Chipped 1 To 5



4: Wheel nsf Scratched Over 50mm



5: Door nsf Chipped 1 To 5

6: Door nsf Scratched Over 25mm Not Thru Paint




7: Door nsr Chipped 1 To 5



8: Wheel nsr Scratched Over 50mm

9: Qtr Panel nsr Scratched Over 25mm Not Thru Paint





11: Bumper Rear Chipped Multiple Chips

No Image

12: Bumper Rear Scratched Over 25mm Not Thru Paint

No Image

13: Boot Lid Scratched Over 25mm Not Thru Paint

No Image

14: Qtr Panel osrScratchedOver 25mm Not Thru Paint



15: Wheel osr Scratched Over 50mm



16: Door osf Scratched UpTo 25mm Thru Paint

17: Door osr Scratched Over 25mm Not Thru Paint



18: Door osf Dented Over 2 UpTo 10mm

No Image

19: Door osf Scratched Over 25mm Not Thru Paint



20: Wing osf Scratched UpTo 25mm Thru Paint

21: Wing osf Scratched Over 25mm Not Thru Paint



22: Wheel osf Scratched Over 50mm



23: Screen Front Chipped UpTo 10mm

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated OK	Oil warning light illuminated OK
Airbag light illuminated OK	DPF light illuminated OK
ABS light illuminated OK	Service indicator light illuminated OK
Windows OK	Radio OK
Sat nav OK	Steering OK