

VEHICLE INSPECTION REPORT

HK15VPA

Nissan Leaf 80kW Acenta 24kWh 5dr Auto

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	27/07/2015	Body Style	Hatchback	Last service miles	34,291
Year	2015	Keys	2	MOT Due	18/06/2026
Mileage	35,066 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Electric	Service documents	Service Book	Gears	1
Colour	RED	Number of stamps	9	Doors	5
VIN	SJNFAAZE0U6034913	Last service date	19/06/2025		

Last service 19/06/2025 at 34291 miles (9 main dealer services). Type 3 charging cable only

Tyres


NSF	WESTLAKE	5.0mm
NSR	WESTLAKE	5.0mm
OSF	BUDGET	6.0mm
OSR	EVENT	5.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Navigation system	• Park assist camera
• PAS	• Rear wiper	• Steering wheel mounted controls	• Digital radio
• Body coloured bumpers	• Electric door mirrors	• Front fog lights	• Air conditioning
• Folding rear seats	• Front armrest	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear electric windows	• Rear headrests	• Steering wheel rake adjustment
• Steering wheel reach adjustment	• Metallic Paint	• 3x3 point rear seat belts	• ABS
• Curtain airbags	• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag
• Rear airbags	• Side airbags	• Tyre pressure monitor	• Central locking
• Remote central locking	• Cloth seat trim	• Alloy wheels	

Photos





Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint



2: Bumper Front
Cracked
UpTo 25mm



3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Up To 50mm



5: Screen Front
Chipped
UpTo 10mm




6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Qtr Panel nsr
Dented
With Paint Damage



10: Bumper Rear
Scratched
Over 100mm Thru Paint




11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Over 50mm



13: Spoiler Rear
Scratched (Painted)
Over 25mm Thru Paint



14: Door osr
Dented
With Paint Damage



15: Door osf
Scratched
Over 25mm Thru Paint



16: Wheel osf
Scratched
Over 50mm



17: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

-
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK