

## VEHICLE INSPECTION REPORT

BG19KFD

### Ford Mondeo 1.5 EcoBoost 165 Zetec Edition 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 5

#### Details

Reg. date	08/03/2019
Year	2019
Mileage	143,694 Miles Warranted
Fuel Type	Petrol
Colour	BLACK
VIN	WF0EXXWPCEKC00092

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	6
Last service date	03/12/2024

Last service miles	125,862
MOT Due	31/01/2026
Gearbox	MANUAL
Gears	6
Doors	5

#### £65 ADDITIONAL FEE

Last service 03/12/2024 at 125,862 miles- 6 main dealer services

#### Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

## Features


- Bluetooth connection
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Tyre pressure monitor
- Alloy wheels
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Chipped  
Multiple Chips




3: Bumper Front Moulding  
Broken  
Replace



4: Wing nsf  
Scratched  
Over 25mm Thru Paint



5: Wheel nsf  
Scratched  
Over 50mm



6: Door nsf  
Dented  
With Paint Damage



7: Door nsr  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



10: Bumper Rear  
Dented  
With Paint Damage



11: Tailgate  
Dented  
Over 30mm



12: Qtr Panel osr  
Dented  
Between 10mm + 30mm



13: Door osr  
Scratched  
Over 25mm Thru Paint



14: Door osf  
Scratched  
Over 25mm Thru Paint



15: Wing osf  
Chipped  
1 To 5



16: Wheel osf  
Scratched  
Over 50mm



17: Roof  
Chipped  
Multiple Chips

## Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK