

VEHICLE INSPECTION REPORT

RX14NZZ

Fiat 500 1.2 S 3dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	01/03/2014
Year	2014
Mileage	59,506 Miles Warranted
Fuel Type	Petrol
Colour	RED
VIN	ZFA3120000J149782

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	9
Last service date	11/02/2025

Last service miles	55,559
MOT Due	31/03/2026
Gearbox	MANUAL
Gears	5
Doors	3

Last service 11/02/2025 at 55,559 miles- 9 service. Book Coolant leak

Tyres


NSF	NEXEN	5.0mm
NSR	NEXEN	5.0mm
OSF	NEXEN	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features


- Bluetooth connection
- Radio/CD
- Space saver spare wheel
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Partial leather seat trim
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake




2: Bumper Front
Poor Previous Repair
Paint Flake




3: Wing nsf
Scratched
UpTo 25mm Thru Paint




4: Door nsf
Dented
Over 30mm



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Qtr Panel nsr
Dented
Between 10mm + 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint




8: Bumper Rear
Scratched
Over 100mm Thru Paint



9: Qtr Panel osr
Scratched
Over 25mm Thru Paint



10: Wheel osr
Scratched
Over 50mm



11: Door osf
Dented
With Paint Damage



12: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



13: Wing osf
Dented
Over 30mm



14: Wheel osf
Scratched
Over 50mm



15: Roof
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK