

VEHICLE INSPECTION REPORT

HT68FEK

Kia Stonic 1.0T GDi 4 5dr Auto

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	03/01/2019
Year	2019
Mileage	88,276 Miles Warranted
Fuel Type	Petrol
Colour	GREY
VIN	KNAD6811VK6241101

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	25/11/2025

Last service miles	87,815
MOT Due	Expired
Gearbox	SEMI AUTO
Gears	7
Doors	5

£100 ADDITIONAL FEE. EXPIRED MOT.

Last service 25/11/2025 at 87,815 miles- 8 services (3 main dealer) Book

Tyres





NSF	CONTINENTAL	3.0mm
NSR	CONTINENTAL	4.0mm
OSF	CONTINENTAL	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Rear headrests
- Drivers airbag
- Central locking
- Cruise control
- PAS
- Audio remote control
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Rear parking sensor
- Digital radio
- Climate control
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Navigation system
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- ABS
- Traction control
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Door Pad osf
Scuffed
Over 25mm



3: Bonnet
Chipped
Multiple Chips




4: Bumper Front
Scratched
Over 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips




8: Door nsf
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Chipped
1 To 5




11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Boot Lid
Dented
Over 30mm



14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Qtr Panel osr
Dented
Between 10mm + 30mm

No Image


16: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Over 2 UpTo 10mm



19: Door osr
Scratched
Over 25mm Not Thru Paint



20: Door osf
Chipped
1 To 5

No Image



21: Door osf
Scratched
Over 25mm Not Thru Paint

22: Wheel osf
Scratched
Over 50mm



23: Wing osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK