

VEHICLE INSPECTION REPORT

GD17JYG

Suzuki Swift 1.0 Boosterjet SZ-T 5dr

| Inspection | Vehicle | | GRADE 3 nama |
|-----------------|---------|---------|--------------------|
| Serious Damage? | VAT | Margin | |
| No | V5 | Present | |

Details

| | | | | | |
|-----------|----------------------------|-------------------|--------------|--------------------|------------|
| Reg. date | 31/05/2017 | Body Style | Hatchback | Last service miles | 127,800 |
| Year | 2017 | Keys | 2 | MOT Due | 25/10/2026 |
| Mileage | 130,308 Miles Warranted | Service history | Yes | Gearbox | MANUAL |
| Fuel Type | Petrol | Service documents | Service Book | Gears | 5 |
| Colour | BLUE | Number of stamps | 10 | Doors | 5 |
| VIN | JSAAZC13S00101339 | Last service date | 14/10/2025 | | |

Last service 14/10/2025 at 127,800 miles- 10 services (2 main dealer) Book Boot struts weak


Tyres


| | | |
|-------|--------|-------|
| NSF | BUDGET | 4.0mm |
| NSR | BUDGET | 4.0mm |
| OSF | BUDGET | 4.0mm |
| OSR | BUDGET | 4.0mm |
| Spare | | |

Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Height adjustable drivers seat
- ABS
- Central locking
- PAS
- Digital radio
- Climate control
- Rear headrests
- Drivers airbag
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Steering wheel mounted controls
- Electric door mirrors
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos






Condition Check



Damage Photos



1: Door Pad osf
Scuffed
UpTo 25mm




2: Bonnet
Dented
With Paint Damage



3: Bumper Front
Scratched
Over 100mm Thru Paint




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint

No Image


6: Wing nsf
Scratched
Over 25mm Not Thru Paint



7: Door nsf
Dented
Over 2 UpTo 10mm

No Image

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsr
Chipped
1 To 5

No Image

10: Door nsr
Scratched
Over 25mm Not Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



13: Bumper Rear
Poor Previous Repair
Poor Paint




14: Boot Lid
Dented
Over 2 UpTo 10mm




15: Qtr Panel osr
Chipped
1 To 5




16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Over 2 UpTo 10mm



18: Door osr
Chipped
1 To 5



19: Door osf
Chipped
1 To 5

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Wing osf
Chipped
1 To 5



22: Screen Front
Chipped
UpTo 10mm



23: Wheel osf
Scratched
Over 50mm

Interior

| | |
|------------------|---------|
| Carpet Condition | Average |
| Seat Condition | Average |

| | |
|----------------------|---------|
| Upholstery Condition | Average |
| Odour | No |

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| | | | |
|----------------------|----|--|----|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| No Excessive Smoking | | | OK |

| | | | |
|--------------------------|----|-------------------------------------|----|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |