

VEHICLE INSPECTION REPORT

GR55MYC

Volkswagen Golf Plus 1.9 SE TDI PD 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 4

Details

Reg. date	20/12/2005
Year	2005
Mileage	168,127 Miles Warranted
Fuel Type	Diesel
Colour	BLUE
VIN	WVWZZZ1KZ6W509725

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	16
Last service date	03/11/2025

Last service miles	167,318
MOT Due	30/01/2026
Gearbox	MANUAL
Gears	5
Doors	5

£50 ADDITIONAL FEE. Last service 03/11/2025 at 167318 miles (16 services (9 main dealer). Book & print.


Tyres

NSF	MICHELIN	3.0mm
NSR	MICHELIN	4.0mm
OSF	MICHELIN	3.0mm
OSR	MICHELIN	3.0mm
Spare		

Features


- PAS
- Electric door mirrors
- Height adjustable drivers seat
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Climate control
- Rear electric windows
- ABS
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Front electric windows
- Rear headrests
- Curtain airbags
- Side airbags
- Alloy wheels
- Body coloured bumpers
- Front head restraints
- Metallic Paint
- Drivers airbag
- Central locking

Photos





Condition Check



Damage Photos



1: Other

N/A

N/A



2: Bumper Front

Chipped

Multiple Chips

No Image

3: Bumper Front
Scratched
Over 25mm Not Thru Paint



4: Wing nsf
Rusted
Over 5mm



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 2 UpTo 10mm

No Image

7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Chipped
1 To 5

No Image

9: Door nsr
Scratched
Over 25mm Not Thru Paint



10: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

No Image

11: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



12: Wheel nsr
Scratched
Up To 50mm




13: Bumper Rear
Scratched
25 to 100mm Thru Paint




14: Bumper Rear
Scratched
Over 25mm Not Thru Paint



15: Boot Lid
Dented
Over 2 UpTo 10mm




16: Qtr Panel osr
Chipped
1 To 5




17: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



18: Wheel osr
Scratched
Up To 50mm



19: Door osr
Poor Previous Repair
Poor Paint



20: Door osf
Poor Previous Repair
Poor Paint



21: Roof
Rusted
Over 5mm



22: Wing osf
Rusted
Over 5mm



23: Wheel osf
Scratched
Up To 50mm



24: Roof
Rusted
Over 5mm



25: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Poor
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK