

VEHICLE INSPECTION REPORT

ND65YJE

Nissan Juke 1.2 DiG-T Tekna 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE 5

Details

Reg. date	27/01/2016
Year	2016
Mileage	94,569 Miles Warranted
Fuel Type	Petrol
Colour	BLUE
VIN	SJNFEAF15U7193466

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	11/07/2025

Last service miles	87,783
MOT Due	11/02/2026
Gearbox	MANUAL
Gears	6
Doors	5

Last Service - 11.07.2025 at 87783 miles (8 services) Glovebox broken

Tyres



NSF	BUDGET	Illegal
NSR	BUDGET	4.0mm
OSF	BUDGET	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Navigation system	• Park assist camera
• PAS	• Rear wiper	• Steering wheel mounted controls	• Audio remote control
• Digital radio	• Body coloured bumpers	• Electric door mirrors	• Air conditioning
• Climate control	• Front armrest	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear electric windows	• Rear headrests	• Metallic Paint
• 3x3 point rear seat belts	• ABS	• Drivers airbag	• Isofix child seat anchor points
• Passenger airbag	• Traction control	• Central locking	• Remote central locking
• Leather seat trim	• Alloy wheels		

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Dented
Over 2 UpTo 10mm



5: Wing nsf
Scratched
Over 25mm Not Thru Paint




6: Door nsf
Dented
With Paint Damage



7: Door nsr
Chipped
Multiple Chips



8: Wheel nsr
Scratched
Over 50mm




9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



10: Bumper Rear
Poor Previous Repair
Poor Paint




11: Boot Lid
Dented
Over 2 UpTo 10mm



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Wheel osr
Scratched
Over 50mm



14: Door osr
Dented
With Paint Damage



15: Door osf
Dented
With Paint Damage



16: Wing osf
Dented
With Paint Damage



17: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK