

VEHICLE INSPECTION REPORT

LR10VVL

Volvo XC90 2.4 D5 Active 5dr

Inspection	Vehicle		nama GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	31/03/2010	Body Style	Estate	Last service miles	180,219
Year	2010	Keys	2	MOT Due	05/02/2026
Mileage	193,052 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Printout	Gears	6
Colour	GREEN	Number of stamps	14		
VIN	YV1CZ7144A1559173	Last service date	31/01/2025		

£65 ADDITIONAL FEE. Last service 31/01/2025 at 180219 miles (14 services (9 main dealer). Anti-skid service requires

Smoking when warm up

Limp mode , dpf blocked

Tyres


NSF	BRIDGESTONE	6.0mm
NSR	CONTINENTAL	6.0mm
OSF	BRIDGESTONE	6.0mm
OSR	BUDGET	6.0mm
Spare		

Features


- Cruise control
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Heated front seat
- Service indicator
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Cloth seat trim
- PAS
- Steering wheel mounted controls
- Electric sunroof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Side airbags
- Alloy wheels
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
Between 10mm + 30mm



4: Wheel nsf
Scratched
Over 50mm



5: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



6: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Dented
Over 30mm



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Tailgate
Dented
Between 10mm + 30mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint



14: Wheel osr
Corroded
Light



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Chipped
Edge Chip



17: Wheel osf
Scratched
Over 50mm



18: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	Fault

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK