

VEHICLE INSPECTION REPORT

HK14HHX

Nissan Juke 1.6 Acenta Premium 5dr Xtronic

Inspection	Vehicle	nama GRADE 4
Serious Damage?	VAT	Margin
No	V5	Present

Details

Reg. date	30/06/2014	Body Style	Hatchback	Last service miles	43,306
Year	2014	Keys	2	MOT Due	25/06/2026
Mileage	43,803 Miles Warranted	Service history	Yes	Gearbox	CVT
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	BLACK	Number of stamps	11	Doors	5
VIN	SJNFBAF15U7007590	Last service date	16/06/2025		

£65 ADDITIONAL FEE

Last Service - 16.06.2025 at 43306 miles (11 services)

Gearbox fault

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Navigation system	• Park assist camera
• PAS	• Rear wiper	• Steering wheel mounted controls	• Digital radio
• Body coloured bumpers	• Electric door mirrors	• Front fog lights	• Air conditioning
• Folding rear seats	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear electric windows	• Rear headrests	• Steering wheel rake adjustment	• Steering wheel reach adjustment
• Metallic Paint	• 3x3 point rear seat belts	• ABS	• Drivers airbag
• Isofix child seat anchor points	• Passenger airbag	• Side airbags	• Central locking
• Remote central locking	• Cloth seat trim	• Alloy wheels	

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



4: Wing osf
Scratched
Over 25mm Thru Paint



5: A Post ns
Dented
With Paint Damage



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door nsr
Scratched
Over 25mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Bumper Rear
Chipped
1 To 5




10: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



11: Door osr
Chipped
1 To 5



12: Door osf
Chipped
Edge Chip



13: Wing osf
Chipped
1 To 5



14: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint



15: Switches And Controls

Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	Fault
			OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK