

VEHICLE INSPECTION REPORT

LB09JYS

Peugeot 107 1.0 Urban 5dr 2-Tronic

| Inspection | | Vehicle | | | nama |
|-----------------|---------------------------|-----------------|-------------------|---------|-------------------|
| Serious Damage? | No | VAT | Margin | | Graph Standard |
| | | V5 | Present | | |
| Details | | | | | |
| Reg. date | 21/08/2009 | VIN | VF3PNCFAC88384543 | Gearbox | SEMI AUTO |
| Year | 2009 | Body Style | Hatchback | Gears | 5 |
| Mileage | 78,252 Miles Warranted | Keys | 2 | Doors | 5 |
| | | Service history | None | | |
| Fuel Type | Petrol | MOT Due | Expired | | |
| Colour | SILVER | | | | |

No Service History vibration at idle and noisy engine Gearbox fault and noise from rear Boot latch sticks and only starts on one key

Tyres

| NSF | LAUFENN | 4.0mm | |
|-------|-----------|-------|--|
| NSR | AUTOGREEN | 4.0mm | |
| OSF | AUTOGREEN | 4.0mm | |
| OSR | AUTOGREEN | 4.0mm | |
| Spare | | | |

Features

- PAS

- Air conditioningRear headrestsPassenger airbagSteel wheels
- Rear wiper
- Climate controlMetallic Paint
- · Central locking
- Radio/CD
- Front electric windowsABS
- Remote central locking
- Body coloured bumpers
- Front head restraints
- Drivers airbag
- Cloth seat trim

Photos
























Condition Check



Damage Photos



1: Bonnet Dented With Paint Damage



2: Bumper Front Scratched Over 100mm Thru Paint



3: Wing osf Dented Over 30% Of Panel



4: Door osf Chipped 1 To 5



5: Door osr Chipped 1 To 5



6: Bumper Rear Scratched Over 100mm Thru Paint




7: Door nsr Chipped 1 To 5



8: Door nsf Chipped 1 To 5



9: Wing nsf Poor Previous Repair Poor Paint



10: Screen Front Chipped UpTo 10mm



11: Sill os Dented With Paint Damage

Interior

Carpet ConditionAverageUpholstery ConditionAverageSeat ConditionAverageOdourNo

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

| Engine Runs | Fault | Gearbox 1st and Reverse Test | OK |
|---------------|-------|------------------------------------------------|----|
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| EML light illuminated OK | | Oil warning light illuminated | OK |
|--------------------------|----|-------------------------------------|----|
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |