

VEHICLE INSPECTION REPORT

GL64OSB

Hyundai i20 1.2 Active 5dr

Inspection	Vehicle		GRADE 3
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	30/11/2014	Body Style	Hatchback	Last service miles	74,595
Year	2014	Keys	2	MOT Due	29/11/2026
Mileage	97,187 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	5
Colour	SILVER	Number of stamps	3	Doors	5
VIN	MALBB51BLFM686415	Last service date	18/07/2023		

Last service 18/07/2023 at 74,595 miles- 3 services (1 main dealer) Book EML light on car has been plugged in and detects camshaft position timing over advanced or system performance bank 1

Tyres

NSF	BRIDGESTONE	3.0mm
NSR	BRIDGESTONE	3.0mm
OSF	BRIDGESTONE	3.0mm
OSR	BRIDGESTONE	3.0mm
Spare		

Features


• PAS	• Rear wiper	• Steering wheel mounted controls	• Audio remote control
• Radio/CD	• Body coloured bumpers	• Electric door mirrors	• Air conditioning
• Climate control	• Front electric windows	• Front head restraints	• Height adjustable drivers seat
• Rear electric windows	• Rear headrests	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag
• Central locking	• Remote central locking	• Cloth seat trim	• Alloy wheels

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
Multiple Chips

No Image



3: Bumper Front
Scratched
Over 25mm Not Thru Paint

4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsr
Chipped
Multiple Chips



7: Door nsr
Chipped
Multiple Chips




8: Wheel nsf
Scratched
Over 50mm




9: Qtr Panel nsr
Dented
Over 2 UpTo 10mm

10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint

12: Boot Lid
Dented
Over 2 UpTo 10mm



13: Wheel osr
Scratched
Up To 50mm

14: Qtr Panel osr
Dented
Between 10mm + 30mm



15: Door osr
Chipped
1 To 5



16: Door osf
Dented
Over 2 UpTo 10mm



17: Wing osf
Dented
Over 2 UpTo 10mm



18: Wheel osf
Scratched
Over 50mm



19: Seat Back Cover osf
Torn
Over 3mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK