

## VEHICLE INSPECTION REPORT

SA60XPY

### Nissan Qashqai 1.5 dCi Acenta 5dr

Inspection	Vehicle		GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

#### Details

Reg. date	27/09/2010	Body Style	Hatchback	Last service miles	156,232
Year	2010	Keys	2	MOT Due	22/10/2026
Mileage	172,607 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	SILVER	Number of stamps	10	Doors	5
VIN	SJNFCAJ10U2135743	Last service date	06/11/2020		

Last Service - 06.11.2020 at 156232 miles (10 services)

Timing Belt Replaced 06.11.2020 @ 156232 miles Poor brakes

Sticky clutch

#### Tyres

NSF	AUTOGREEN	6.0mm
NSR	BUDGET	5.0mm
OSF	AUTOGREEN	6.0mm
OSR	BUDGET	5.0mm
Spare		

## Features


- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- PAS
- Radio/CD
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

## Photos





## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Bumper Front  
Insecure  
Action Required



3: Bumper Front  
Dented  
With Paint Damage



4: Bonnet  
Dented  
Over 30mm



5: Wheel nsf  
Scratched  
Over 50mm



6: Wing nsf  
Scratched  
Over 25mm Thru Paint



7: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Thru Paint



8: Door nsf  
Dented  
Between 10mm + 30mm



9: Door nsr  
Scratched  
UpTo 25mm Thru Paint



10: Qtr Panel Moulding ns  
Scuffed (Unpainted)  
UpTo 100mm



11: Wheel nsr  
Scratched  
Over 50mm



12: Qtr Panel nsr  
Dented  
Between 10mm + 30mm



13: Bumper Rear  
Poor Previous Repair  
Paint Flake



14: Wheel osr  
Scratched  
Up To 50mm



15: Door osr  
Scratched  
Over 25mm Thru Paint



16: Door osf  
Scratched  
UpTo 25mm Thru Paint



17: Wing osf  
Scratched  
UpTo 25mm Thru Paint



18: Wheel osf  
Scratched  
Over 50mm



19: Lamp nsr  
Broken  
Replace

## Interior

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Average

<b>Upholstery Condition</b>	Average
<b>Odour</b>	No

## Vehicle Inspection Report

---

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	Fault	Clutch Slip Test from Static	Fault
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK