

## VEHICLE INSPECTION REPORT

FD64FYC

### Ford Focus 1.6 TDCi 115 Zetec S 5dr

#### Inspection

Serious Damage? No

#### Vehicle

VAT	Margin
V5	Present

nama  
GRADE 4

#### Details

Reg. date	08/12/2014
Year	2014
Mileage	69,680 Miles Warranted
Fuel Type	Diesel
Colour	BLACK
VIN	WF0KXXGCBKEB81638

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	04/08/2025

Last service miles	67,165
MOT Due	07/12/2026
Gearbox	MANUAL
Gears	6
Doors	5

Last Service - 04.08.2025 at 67165 miles (8 services) Oil light on dash

Temperature gauge fluctuates

Tyre Pressure light is on

#### Tyres

NSF	Apollo	4.0mm
NSR	Apollo	4.0mm
OSF	Apollo	4.0mm
OSR	Budget	4.0mm
Spare		

## Features


- Bluetooth connection
- Audio remote control
- Air conditioning
- Front head restraints
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- PAS
- Radio/CD
- Climate control
- Height adjustable drivers seat
- ABS
- Side airbags
- Cloth seat trim
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels
- Steering wheel mounted controls
- Electric door mirrors
- Front electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

## Photos






## Condition Check



## Damage Photos



1: Wing osf  
Dented  
Over 30mm



2: Wheel osf  
Scratched  
Over 50mm



3: Door osr  
Scratched  
Over 25mm Thru Paint



4: Door osr  
Scratched  
Over 25mm Not Thru Paint



5: Qtr Panel osr  
Scratched  
Over 25mm Not Thru Paint



6: Wheel osr  
Scratched  
Up To 50mm



7: Rear TowEye Cvr  
Missing  
Replace



8: Bumper Rear  
Scratched  
Over 25mm Not Thru Paint



9: Bumper Rear  
Chipped  
1 To 5



10: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



11: Wheel nsr  
Scratched  
Up To 50mm



12: Door nsr  
Scratched  
Over 25mm Not Thru Paint



13: Door nsf  
Chipped  
Edge Chip



14: Door nsf  
Scratched  
Over 25mm Not Thru Paint




15: Wheel nsf  
Scratched  
Over 50mm



16: Wing nsf  
Scratched  
Over 25mm Not Thru Paint



17: Bumper Front  
Chipped  
1 To 5



18: Bonnet  
Dented  
Over 30mm



19: C Post os  
Dented  
Over 30mm

## Interior

**Carpet Condition**  
**Seat Condition**

Average  
Average

**Upholstery Condition**  
**Odour**

Average  
No

## Vehicle Inspection Report

### Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK