

VEHICLE INSPECTION REPORT

GH17GVP

Nissan Qashqai 1.2 DiG-T N-Vision 5dr

Inspection	Vehicle		GRADE 5
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	30/03/2017	Body Style	Hatchback	Last service miles	99,114
Year	2017	Keys	2	MOT Due	04/04/2026
Mileage	99,689 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLUE	Number of stamps	9	Doors	5
VIN	SJNFEAJ11UZ006074	Last service date	10/12/2025		

Last Service - 10.12.2025 at 99114 miles (9 services) Eml light is on

Tyres



NSF	FALKEN	3.0mm
NSR	GENERAL TIRE	5.0mm
OSF	FALKEN	4.0mm
OSR	GENERAL TIRE	5.0mm
Spare		

Features


- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- ESP
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos






Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Poor Previous Repair
Poor Paint



3: Wheel nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5




5: Wing nsf
Scratched
Over 25mm Not Thru Paint



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Boot Lid
Dented
Over 2 UpTo 10mm




12: Qtr Panel osr
Chipped
1 To 5




13: Bumper Rear
Insecure
Action Required




14: Wheel osr
Scratched
Over 50mm



15: Door osr
Dented
With Paint Damage



16: Door osf
Dented
With Paint Damage



17: Wing osf
Dented
With Paint Damage



18: Wheel osf
Scratched
Up To 50mm

Interior

Carpet Condition	Average
Seat Condition	Average

Upholstery Condition	Average
Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		