

VEHICLE INSPECTION REPORT

SW68CXZ

Volkswagen T-Roc 1.5 TSI EVO SEL 5dr

Inspection

Serious Damage? No

Vehicle

VAT	Margin
V5	Present

nama
GRADE
3

Details

Reg. date	17/12/2018
Year	2018
Mileage	69,703 Miles Warranted
Fuel Type	Petrol
Colour	SILVER
VIN	WVGZZZA1ZKV025709

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	4
Last service date	06/01/2025

Last service miles	53,414
MOT Due	19/03/2026
Gearbox	MANUAL
Gears	6
Doors	5

£65 ADDITIONAL FEE. Last service 06/01/2025 at 53414 miles (4 main dealer services). Sunroof closing fault

Tyres

NSF	BUDGET	3.0mm
NSR	NANKANG	3.0mm
OSF	NANKANG	3.0mm
OSR	NANKANG	3.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Digital radio
- Opening panoramic glass roof
- Front electric windows
- Rear electric windows
- ABS
- Side airbags
- Partial leather seat trim

- Cruise control
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Rear headrests
- Drivers airbag
- Traction control
- Alloy wheels

- Front parking sensor
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Central locking


- PAS
- Audio remote control
- Electric sunroof
- Front armrest
- Rear armrest
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
UpTo 3mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
Over 100mm Thru Paint




4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Chipped
1 To 5



6: Door nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Not Thru Paint



8: Door nsr
Dented
With Paint Damage




9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Dented
With Paint Damage



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
Over 25mm Not Thru Paint



13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



16: Wheel osr
Scratched
Over 50mm



17: Door osr
Dented
Over 2 UpTo 10mm

No Image

18: Door osr
Scratched
Over 25mm Not Thru Paint



19: Door osf
Chipped
1 To 5

No Image

20: Door osf
Scratched
Over 25mm Not Thru Paint



21: Wing osf
Chipped
1 To 5



22: Screen Front
Chipped
UpTo 10mm



23: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition Average
Seat Condition Average

Upholstery Condition Average
Odour No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	Fault	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		