

VEHICLE INSPECTION REPORT

SE64LXJ

Nissan Qashqai 1.2 DiG-T N-Tec+ 5dr

Inspection	Vehicle		nama GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	27/01/2015	Body Style	Hatchback	Last service miles	88,071
Year	2015	Keys	1	MOT Due	28/05/2026
Mileage	94,513 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Printout	Gears	6
Colour	RED	Number of stamps	2	Doors	5
VIN	SJNFEAJ11U1236408	Last service date	27/02/2025		

£65 ADDITIONAL FEE

Last Service - 27.02.2025 at 88071 miles (2 services)

Engine rattle

Tyres



NSF	BUDGET	4.0mm
NSR	MAXXIS	3.0mm
OSF	BUDGET	4.0mm
OSR	CONTINENTAL	4.0mm
Spare		

Features


- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips




2: Bumper Front
Scratched
Over 100mm Thru Paint




3: Wing nsf
Scratched
Over 25mm Thru Paint



4: Wheel nsf
Scratched
Over 50mm



5: Door nsf
Dented
Over 30mm



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Dented
Over 2 UpTo 10mm



8: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Bumper Rear
Scratched
Over 25mm Not Thru Paint



12: Boot Lid
Dented
Over 2 UpTo 10mm



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint




14: Wheel osr
Scratched
Over 50mm




15: Door osr
Dented
Over 2 UpTo 10mm

No Image



17: Door osf
Chipped
1 To 5

No Image



19: Wing osf
Scratched
Over 25mm Thru Paint

16: Door osr
Scratched
Over 25mm Not Thru Paint



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		