

VEHICLE INSPECTION REPORT

LF19UDL

Citroen C4 Cactus 1.5 BlueHDI 120 Flair EAT6 5dr

Inspection	Vehicle	nama GRADE 2	
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	01/03/2019	Body Style	Hatchback	Last service miles	56,788
Year	2019	Keys	2	MOT Due	07/12/2026
Mileage	75,651 Miles Warranted	Service history	Yes	Gearbox	AUTOMATIC
Fuel Type	Diesel	Service documents	Service Book	Gears	6
Colour	WHITE	Number of stamps	7	Doors	5
VIN	VF70BYHXXJE557619	Last service date	01/10/2024		

Last service 01/10/2024 at 56,788 miles- 7 services (3 main dealer) Book EML light on car has been plugged in and detects catalyst efficiency below threshold bank 1

Air bag light on
Adblue light on
Spanner light on

Tyres



NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Navigation system	• Park assist camera
• PAS	• Rear wiper	• Steering wheel mounted controls	• Audio remote control
• Digital radio	• Body coloured bumpers	• Electric door mirrors	• Air conditioning
• Climate control	• Front armrest	• Front electric windows	• Front head restraints
• Height adjustable drivers seat	• Rear headrests	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• Isofix child seat anchor points	• Passenger airbag
• Side airbags	• Traction control	• Central locking	• Remote central locking
• Cloth seat trim	• Alloy wheels		

Photos





Condition Check



Damage Photos



1: Bumper Rear
Chipped
Multiple Chips

No Image

2: Bumper Rear
Scratched
Over 25mm Not Thru Paint



3: Boot Lid
Chipped
1 To 5



4: Qtr Panel osr
Chipped
1 To 5



5: Wheel osr
Scratched
Over 50mm



6: Door osr
Dented
Between 10mm + 30mm



7: Door osr
Scratched
Over 25mm Not Thru Paint



8: Door osf
Chipped
1 To 5



9: Wing osf
Chipped
1 To 5



10: Wheel osf
Scratched
Up To 50mm



11: Bumper Front
Scratched
25 to 100mm Thru Paint

No Image

12: Bumper Front
Scratched
Over 25mm Not Thru Paint



13: Bumper Front Moulding
Broken
Replace

14: Bonnet
Chipped
1 To 5

No Image

15: Wing nsf
Scratched
Over 25mm Not Thru Paint




16: Wheel nsf
Scratched
Over 50mm




17: Door nsf
Dented
Over 2 UpTo 10mm



18: Door nsr
Chipped
1 To 5



19: Wheel nsr
Scratched
Up To 50mm



20: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



21: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK