

VEHICLE INSPECTION REPORT

GX64UEC

Seat Leon 1.4 TSI 125 SE 5dr [Technology Pack]

Inspection	Vehicle		GRADE 4
Serious Damage?	VAT	Margin	
No	V5	Present	

Details

Reg. date	15/09/2014	Body Style	Hatchback	Last service miles	119,027
Year	2014	Keys	2	MOT Due	05/08/2026
Mileage	131,067 Miles Warranted	Service history	Yes	Gearbox	MANUAL
Fuel Type	Petrol	Service documents	Service Book	Gears	6
Colour	BLACK	Number of stamps	5	Doors	5
VIN	VSSZZZ5FZFR022934	Last service date	07/01/2025		

£65 ADDITIONAL FEE.

Last service 07/01/2025 at 119,027 miles- 5 services (2 main dealer) Book Driver side front window will not open
Oil service due message displayed

Tyres



NSF	LANVIGATOR	5.0mm
NSR	MARSHAL	5.0mm
OSF	LANVIGATOR	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


• Bluetooth connection	• Cruise control	• Navigation system	• PAS
• Rear parking sensor	• Rear wiper	• Service indicator	• Steering wheel mounted controls
• Digital radio	• Body coloured bumpers	• Electric door mirrors	• Front fog lights
• Air conditioning	• Folding rear seats	• Front armrest	• Front electric windows
• Front head restraints	• Height adjustable drivers seat	• Rear electric windows	• Rear headrests
• Steering wheel rake adjustment	• Steering wheel reach adjustment	• Metallic Paint	• 3x3 point rear seat belts
• ABS	• Drivers airbag	• ESP	• Isofix child seat anchor points
• Passenger airbag	• Side airbags	• Central locking	• Remote central locking
• Cloth seat trim	• Alloy wheels		

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front
Insecure
Action Required



4: Wheel nsf
Scratched
Over 50mm



5: Wing nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsf
Scratched
Over 25mm Thru Paint



7: Door osr
Chipped
1 To 5



8: Wheel osr
Scratched
Over 50mm



9: Qtr Panel nsr
Dented
Between 10mm + 30mm



10: Bumper Rear
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Scratched
Over 25mm Thru Paint



15: Wing osf
Scratched
Over 25mm Thru Paint



16: Roof
Scratched
Over 25mm Thru Paint



17: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition
Seat Condition

Average
Average

Upholstery Condition
Odour

Average
No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
No Excessive Smoking			OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	Fault	Radio	OK
Sat nav	OK	Steering	OK